

~~TOP SECRET~~

25X1A

Dispatch No. [REDACTED] 0022

9 April 1956

Page 1 of 1 page

Copy of 4 copies

25X1A

TO: [REDACTED]

FROM: [REDACTED]

SUBJECT: [REDACTED]

DOCUMENT NO. 143316
NO CHANGE IN CLASS. ☐
☐ DECLASSIFIED
CLASS. CHANGED TO: TS (S) 0
NEXT REVIEW DATE: 8-1-06
AUTH: HR 70-2
DATE: 8-1-86 REVIEWER: 100368

1. Detachment "A" A-1006; A-1008

25X1A

These reports will be the same as for [REDACTED] A-1005.

A-1008 had complete camera failure after 200⁴ miles of tracker film exposed.

No configuration A-2 operations for entire flight due to blown circuit breaker in scope compensator system.

25X1A

Enclosures:

- 1 Documentation of flights (weather)
Sortie A-1006
TS #73, copy 1 of 2 (2 pages)
- 2 Documentation of flights (weather)
Sortie A-1008
TS #74, copy 1 of 2 (3 pages)

TS-143316
TS #73
Copy 1 of 4
page 1 of 1 page

~~TOP SECRET~~